Crawford County Recovery Davise Measure

PEE BOOK 2004-1701 6/14/2004 @ 09:35PM PIC PLAT CORNER CERBOOK: Page:04-1701 #: 1 Total Fees: \$11.00 INDEXED FOLLOW UP PROOFED SCANNED

This document prepared by: Semke & Associates - 712-792-2276 Micheal G. Semke, L.S. #10318 - 716 N. Crawford St. - Carroll, Iowa

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 27, Township 85 North, Range 41 West, of the Fifth Principal Meridian, Crawford County, Iowa. Previously recorded in Book , Page in County Recorder's Office.

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

W 1/4 Corner	Fnd. Broken C.M. 8" Deep		
	Straightened 3/8" Core Wire up -		
	Top is <u>5" Deep</u>		
SW Corner	Fnd. 60d Spk. w/Flagging @		
	Record Ties 5" Deep		
Note: All pins set are 1/2" x 2	24" Rerod w/Yellow Cap #10318 unless noted otherwise.		

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



Note: all ties slope chained unless noted otherwise.



	List Corners	to be inde	exed
Corners	Section	Twp	Range
W 1/4 Cor	27	85	41
E 1/4 Cor	28	85	41
SW Cor	27	85	41
NW Cor	34	85	41
NE Cor	33	85	41
SE Cor	28	85	41